

March 31, 1987

TO: File

FROM: Frank Jensen, Soil Reclamation Specialist *Jensen*

RE: Southwestern Portland Cement, Navajo Sandstone Quarry,
ACT/023/010

On March 11, 1987, Dave Wham, Frank Filas, and I visited the subject site, as a result of a call from Bob Weeks (857-2380) of the company concerning their seeding test plot required for permitting.

In the last few days, they had taken a road grader and "scalped" the existing vegetation off approximately 1/4 acre of land for the test plot.

Photos of the test plot follow:



Photo #1 - Test plot with a "ribbon boarder"

Page 2
Memorandum - ACT/023/010
March 31, 1987



Photo #2 - Close-up of test plot. The seed had been broadcast on the surface and not covered.

On March 12, 1987, I called the company and talked to Bob Feanow. I told him I thought he should get the seed raked in approximately 1/2" deep and fence the plot.

On March 13, 1987, Bob Weeks called and said they were raking in the seed and fencing the plot that day.

clj
cc: L. Braxton
F. Filas
D. Wham
1115R/48